

ZEPHYR HELMET

ZEPHYR ADVANCE 4500 HELMET

5 adjustment modes from an LCD screen with digital keys:

- Welding: variable shades 4/9-13, 4 optical sensors, regulation of the sensitivity and return to a clear shade.
- Grinding: activation of the filter in clear shade level 4.
- Cutting, low current welding: adjustable shades 5 to 9 for TIG process low intensity, microplasma, oxy-fuel gas welding.
- "X mode": adjustable shade 4 to 9-13 with magnetic sensors for outside or obscured arc welding.
- Infotrack system: provides useful information (current time, total welding time, alarm, temperature).



**NEW
GRINDING MODE
WITH EXTERNAL
BUTTON**

**2
YEAR
WARRANTY**

W000372468

**TOP OF THE RANGE SOLUTION
FOR ANY APPLICATION**

Optical Class	1/1/1/2
Switching time light to dark	0.05 ms
Switching time dark to light	10 positions from 0.1s to 1s setting per digital key
Delay Setting	10 positions setting per digital key
Mode	
Welding	Yes shade 9 to 13 per digital key
Grinding	Yes shade 4 (per external button)
Cutting	Yes shade 5 to 9 per digital key
X Mode	Yes
Infotrack system	Yes
Sensors	4 independent optical sensors - Magnetic in "X" mode
Viewing area	97 x 60 mm
Constant UV-IR protection	Yes
Battery type	2 lithium CR2450 3 Volts
Mix power (battery/cell)	Yes
Temperature scale	Use: -5 °C to + 55 °C Storage: -30 °C to 70 °C
Weight	510g (helmet + LCD filter)
Standard	LCD filter: CE EN 379 Helmet: CE EN 175
Part Number	W000372468

The Zephyr solution, you will find in a rugged carry bag:



- The Zephyr helmet
- The Zephyr air flow system
- Protected hose connection
- A shoulder strap
- A battery charger
- An air flow-meter
- One extra filter



INDEPENDENT WHOLESALE WELDING SUPPLY

Ph: 02 8834 2400 Fax: 02 8834 2498 Email: iwws@iwws.net Website: www.iwws.net