



2 ROLL WIRE FEEDERS





Part Number	Includes		
PX20T	2 Roll Wire Feeder		
PX20MT	2 Roll Wire Feeder (with meters and voltage control)		

Features:

- 3 m (10ft) Input cable with 14 pin Miller style plug included.
- 3 m (10ft) gas hose included.
- · Wire job button.
- Gas purge button.
- · Adjustable burn back control.
- Trigger hold (reduces operator fatigue on longer welds)
- Two gear driven rolls with Tool-Less roll change.
- 0.9 1.2 mm (.035/.045") Solid wire drive rolls included.
- Accepts Miller style mig gun connection.

Technical Data:

- Power source type: Constant voltage (CV) DC.
- Weld circuit rating: 500 amp @ 100V, 100% duty cycle.

Input Power	Wire Diameters	Wire Feed Speed	Weight	Dimensions
24VAC 50/60 Hz	0.6 - 2.0 mm (.023 - 5/64")	1.9 - 23 m/min (75 - 900 IPM)	16.5 kg (36 lb)	H: 356 mm (14") W: 280 mm (11") D: 648 mm (25½")





Front view

- 1. Mig gun connection (Miller style)
- 2. Trigger lock switch
- 3. Trigger cord connection (Miller style)
- 4. Wire jog button
- 5. Gas purge button
- 6. Wire speed control
- 7. Voltage control (MT model only)
- 8. Volt & Amp meters (MT model only)



Rear view (Both models)

- 1. Power switch (on/off)
- 2. Fuse holder (10 amp)
- 3. Gas hose connection (5/8-18 female). 3m (10ft) hose included
- 4. 3m (10ft) input cable with 14 pin Miller style plug

